ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
2

Ward Name
Chowdeshwari Ward

Street ID
W0296, W0385, W0393, W0292, W0294, W0298, W0401

Street Name
1st Crs, 8th Crs Gramatana, NA, 3rd Crs Lakshmi Sagar Lyt, Manjunath Floor Mill Rd

Significant Landmark
Kondappa Layout

Segment No.
2/C-W0296/S014905

Total Length (m)
256.23

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	104.91	77.592127	13.108367	77.592683	13.108797	WO 401	WO 393
2	13.92	77.592641	13.108916	77.592690	13.108800	WO401	WO 393
3	56.88	77.591946	13.108773	77.592458	13.108885	WO 292	WO 294
4	36.90	77.592336	13.108695	77.592673	13.108745	WO 296	WO 298
5	10.30	77.592346	13.108602	77.592336	13.108695	WO 296	WO 298
6	33.32	77.592041	13.108562	77.592346	13.108600	WO 296	WO 298

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to drains at Kondappa layout in ward No:02 of Yelahanka Sub Division

Sanctioned Estimated Amount (Rs.)
250000

Sanctioned Year
2018-19

Year
2018 - 2019

Type of Work
Others

Other Work Type

Tender
Tender

Work Details
Improvements to drains at Kondappa layout in ward No:02 of Yelahanka Sub Division

Job No. / Work Code
002-18-000029

Work Order No.
EE/YNK-D/EPMT-02/WO/73/2018 -19

Work Order Date
31/10/2018

Period of Extention
UNDER LIMIT

Defect Liability Period From
31/10/2018

Defect Liability Period To
30/10/2019

Multiple road involved with the same Job No/ Work Code #
No

Contractor Details

Name of Contractor
PRAKASH NAIK

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Scanned by CamScanner

ne No.	E-Mail ID
12827578	

Field Inspection Details

Number of Trees	Any Other Information	Name
5		chandrakanth raju
Date of Inspection	**Remarks**	
14/12/2018		

Category	Image	Photo Remark
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: YELAHANKA **Ward No:** 2 **Ward Name:** Chowdeshwari Ward **Street ID:** W0296, W0385, W0393, W0292,

Scanned by CamScanner